Release Notes

Windows driver version 1.1.0

1. New Features

    a. The following new features were implemented in this release of the driver.

New Feature Summary	Feature ID
The upper right cog menu option to pair a new wireless device to a USB dongle is now greyed out unless a USB wireless dongle is attached to the system.	18
Updated text in dialog for pairing a new wireless device to a USB wireless dongle.	8
In the settings panel, the Set button on the Quick Keys image is now highlighted when the cursor is hovering over a button set.	20
In a multiple display environment always present the settings panel on the current active display.	24
Added ability to import settings from a previous version of the driver.	58
Improved visibility of the 'gear" icon in the settings panel.	46
Added tumble function for Zbrush and Fusion 360	61
Added Mouse Middle Click to Quick Keys Dial Keystroke dialog.	74
In the wireless pairing tool, added ability to clear a single pairing to a wireless device.	
Added ability to save user settings during driver uninstallation.	
On the driver installer we made it easier to see the license agreement check box and text at the lower left of the dialog.	
Added a confirmation dialog when importing settings.	

2. Defect Fixes

    a. The following defects were fixed in this release of the driver.

Defect Summary	Defect ID
Windows Ink checkbox not saved when exiting the settings panel or disconnecting the tablet.	651
Intermittently when you add custom settings for a new application, the settings for the Quick Keys are sometimes not saved correctly when closing then reopening the settings panel.	1627
Tablet corner lights not always saving the color that is was set to in the setting panel.	1596
The Quick Keys dialog to "Replace all settings with the following configuration" can cause the pen to become nonresponsive.	1614
When adding a display to the system, the tablet to screen mapping does not see the new display to map to.	
When using a tablet button to open the setting panel, the settings panel shows up partially off the screen.	1584
Mouse mode pen speed is too slow at lowest setting.	1506
Intermittently the driver doesn't remember the orientation of the Quick Keys and uses the default setting to display text on the OLED.	1385
Missing Xencelabs recommended defaults when adding Corel Painter to the custom application list.	1570
Fixed Add Application dialog so that the Xencelabs applications default option is only available when adding an application that has Xencelabs application defaults.	1547
Fixed an issue on the Quick Keys Dial Mode Function Settings where the dial sensitivity settings are reversed. The dial sensitivity slider now has "Slow" on the left and "Fast" on the right.	1566

3. Known Issues

    a. The following are known issues in the driver and workaround if one exists.

Known Issue Summary	Workaround (if one exists)	Defect ID
No known serious issues at this time.		